around the vertical rebar.



Fireplace/Chimney Repair Inspection Checklist

This is not a comprehensive list of requirements, only a general guide for installation

Reference Information	Extent of Rebuild
 2001 CBC, Chapter 31: Special Construction, Section 3102 City of San Jose Policy UBC 31-1-94 (details of fireplace and chimney repair) http://www.ci.san-jose.ca.us/building General Requirements 	 Existing chimneys that are not built in conformance with current code requirements must be removed down to the shoulder of the firebox and completely rebuilt. Complying chimneys have existing vertical #4 rebar, ¼" stirrups installed, rebar cells fully grouted, a chimney flue liner installed and
_	properly grouted.
☐ A minimum of 4-#4 vertical steel rebars are required.	Progress Inspection
Two additional #4 vertical steel rebars are required if any chimney dimension is greater than 40".	Permit Card available on job site and access to the roof provided.
#5 vertical steel rebars are required if chimney extends more than 5' above the last lateral tie but less than 8'.	Construction must be completed up to the first lateral tie. If multiple lateral ties are required, multiple progress inspections are required
Engineering calculations with a wet stamp and signature are required if chimney extends more than 8' above the last lateral tie.	☐ Vertical rebar must be installed, fully grouted with a minimum of 20" of steel reinforcing bars exposed.
Minimum ¼" stirrup must be placed at a maximum of 18" on center.	☐ The steel straps must be completely installed and visible for inspection.
☐ Stirrups must be one piece and have lapped	☐ Stirrups must be on the job site at the time of the progress inspection.
extensions of not less than 8".	Final Inspection
☐ Two stirrups must be placed at each bend in vertical rebar.	☐ Permit Card available on job site.
☐ Two ¼" stirrups are required at the top of the chimney	☐ Final inspection includes spark arrester and flashing around chimney.
☐ Two 3/16" by 1" steel straps (lateral ties) must be placed at each floor and roof line.	Access to the roof must be provided. Inspectors DO NOT carry ladders.
Straps must be cast at least 12" into chimney with a 180-degree bend with a 6" extension	

vid:1-1 8/7/2003

Ч	Two ¼" stirrups are required at each strap.
	Each strap must be bolted with two ½" bolts (lag screws are not acceptable) to the structural members of the building, such as floor joists or rafters, or a 2X4 cross tie nailed to a minimum of 4 joists with 2-16d nails to each joist.
	The chimney must extend 2' above any part of the building within 10' of the chimney

☐ Chimney must be fitted with an approved spark arrester unless located more than 200' from any mountainous, brush-covered or forest-covered land or land covered with flammable material.

vid:1-1 8/7/2003